

DATE

TOP SECRET

TO :

FROM :

ACTION:

INFO :

IN 80668

OPS 1-10

TO

INFO

TOP SECRET 160620Z CITE

25X1A

CITE

25X1A

IMMEDIATE

25X1A

A. BX 6739

B. FILM EVALUATION REPORT

C. 1/F/3897/67RTS

D. FULTRON 202/14DN/48 SEC/85 DEGREES F /BAR 1.24

E. 2.68/2.82

F. 3404/2153-293-1-9-7/DNA

G. (1) GOOD

(2) GOOD WITH EXCEPTION NOTED IN ITEM I.

(3) MEDIUM

(4) GOOD

(5) OPERATIONAL

(6) NORMAL

H. DISPOSITION:

1. 0 NEG AND 3 DUPE POS FORWARDED TO NATIONAL CUSTOMERS.

TOP SECRET

GROUP 1
EXCLUDED FROM AUTO-
MATIC DOWNGRADING
AND DECLASSIFICATION

25X1A

IN 80668

T O P S E C R E T

PAGE 2

2. 6 DUPE POS AND 2 DUPE NEG FORWARDED TO THEATER CUSTOMS.

1. NORMAL START-UP AND SHUTDOWN WITH CAGING & SHUTTLE MOTION FOR INITIAL 12 FRAMES AND LAST 14 FRAMES. RECYCLE AT FRAME 635 TO 664. REF H-5433 BEGINNING AT FRAME 664 AND EXTENDING TO FRAME 720, THE FWD FRAMES ARE UNDEREXPOSED BY APPROXIMATELY 2 F STOPS. A VERTICAL MINUS DENSITY STREAK WAS NOTICED 16" FROM DATA CHAMBERS IN AFT FRAMES AND 1 1/4" FROM INTERIOR EDGE OF FWD FRAMES, BEGINNING WITH FRAME 664 AND CONTINUED FOR APPROXIMATELY 300 FRAMES. INTERMITTENT PLUS DENSITY LINE 2" FROM TRAILING EDGE ON ALL FRAMES. BANDING OCCURRED IN FRAMES 245 TO 270. MINUS DENSITY LINES OCCURRED 3/4" AND 4" FROM EDGE IN AFT FRAMES. 1/2" MINUS DENSITY STREAKS WERE EVIDENT ON BOTH EDGES OF FILM THROUGHOUT MISSION. A YELLOW DISCOLORATION AND MINUS DENSITY SPOTS WERE NOTICED THROUGHOUT THE MISSION WITH STREAKS OCCURRING FROM FRAME 1067-1073. DISCOLORATION STREAKS AND SPOTS WERE NOTED ONLY ON MISSION STOCK AND NOT ON PRESPLICED STARTUP AND SHUTDOWN CONSISTING OF 300 FT OF MATERIAL ON EACH END OF MISSION. MINOR HANDLING SCRATCHES ARE EVIDENT INTERMITTENTLY THROUGHOUT MISSION.

T O P S E C R E T TOR 160822Z DEC 67

T O P S E C R E T